

January 18<sup>th</sup>, 2010

Steve Buth  
Building Supervisor  
MultiBand Tower  
Fargo, ND

Dear Environmental Air Solutions,

On the morning of January 8<sup>th</sup> 2010, there had been a fuel oil spill in the parking ramp which is below the Multiband Tower.


The elevator in the middle of the building was creating a vacuum which allowed the smell of fuel oil to spread throughout different locations inside the building. Environmental Air Solutions immediately brought over several Odorox Hydroxyl Generators to assist in the odor remediation.

Two of the Boss XL3 units with blowers were placed in the main entrance to the elevator from the parking ramp. The hydroxyl generators reduced a substantial amount of fuel oil odor from rising up the elevator chamber within a few hours. Two Boss XL2 units were placed in several different locations throughout the entire building during the course of 7 days.

Being there are 10 businesses employing over 300 people in this facility, it was important to use the Odorox™ hydroxyl generators and keep the businesses operating normally.

I have attached pictures below.

Sincerely,



Steve Buth  
Building Supervisor  
MultiBand Tower  
Fargo, ND

